Map ID MAP FINDINGS

Direction Distance

EDR ID Number Elevation Database(s) EPA ID Number Site

554 **MANHOLE #36383** NY Spills S104880152 West **NEPTUNE AV & W 28TH ST** N/A

1/2-1 BROOKLYN, NY

0.841 mi. 4439 ft.

Relative: SPILLS: Higher MANHOLE #36383 Name:

Address: NEPTUNE AV & W 28TH ST Actual:

City, State, Zip: BROOKLYN, NY 1 ft. Spill Number/Closed Date: 0008915 / 2001-05-07

> Facility ID: 0008915 Facility Type: ER DER Facility ID: 108903 Site ID: 125919 DEC Region: 2 Spill Cause: Unknown Spill Class: C4 2401 SWIS: Spill Date: 2000-11-01 Investigator: **KMFOLEY** Referred To: Not reported Reported to Dept: 2000-11-01 CID: 390

Water Affected: Not reported Spill Source: Unknown Spill Notifier: Local Agency Not reported Cleanup Ceased: Cleanup Meets Std: False Last Inspection: Not reported Recommended Penalty: False **UST Trust**: False Remediation Phase: 0

Date Entered In Computer: 2000-11-01 Spill Record Last Update: 2001-06-19 Spiller Name: UNKNOWN Spiller Company: Unknown Spiller Address: UNKNOWN Spiller Company: 999 Contact Name: **BILL MURPHY**

"Prior to Sept, 2004 data translation this spill Lead_DEC Field was DEC Memo:

FOLEY DEC INSPECTOR'S NOTES CON ED E2MIS REPORT 11-01-00 Found

approx. 1qt. of an unknown oily substance floating on approx. 500gals. of water in MH36383. while doing open mains. Liquid is contained, no sewersor waterways affected. No leaking equipment, no sump. Liquid PCB sample taken. Lab Seq# 00-10441 <1ppm Update 11-14-00 13:10hrs. Cleanup completed by Flush employee Russo. No sump

in structure. 11-15-00 Clenaup completed by double washing structure with slix. Liquids were removed by tanker and solids were removed by vactor. No leaking company equipment. Incident closed. Aroclor 1242 1ppm Aroclor 1248 1ppm Aroclor 1254 1ppm Aroclor 1260 1ppm"

Remarks: "1 qt on 500 gals of water - sample taken clean up pending lab

results con ed #134194"

All Materials:

Site ID: 125919 Operable Unit ID: 831337 Operable Unit: Material ID: 546418 Material Code: 0066A

Map ID Direction Distance Elevation

Site

MAP FINDINGS

EDR ID Number
Database(s) EPA ID Number

Material Name: unknown petroleum
Case No.: Not reported
Material FA: Petroleum
Quantity: 1.00
Units: G
Recovered: .00

Oxygenate: Not reported